



IECEX CoC Certified Service Facility

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

Certificate No.: **IECEX DEK S0029** Page 1 of 1 [Certificate history:](#)
Issue 0 (2017-06-28)

Status: **Current** Issue No: 0

Date of Issue: 2017-06-28

Applicant: **FACTA Spijkensisse B.V.**
Röntgenweg 6
Spijkensisse 3208 KG
Netherlands

Type of Service: **Repair and Overhaul according to IEC 60079-19**

Type of Protection: **03-5 Program - Repair Overhaul and Reclamation, Flameproof Enclosure "d", Increased Safety "e", Oil Filled "o", Other, Pressurisation "p", Type of Protection "n"**

Scope of Service: Ex d, Ex e, Ex n, Ex o, Ex p, and Ex t motors, transformers, generators and ventilators. Non-electrical equipment, mainly pumps and gearboxes with types of protection c and k. Onsite repair

Locations covered by this Certificate:

FACTA Spijkensisse B.V.
Röntgenweg 6
Spijkensisse 3208 KG
Netherlands

Facility Audit Report:

[NL/DEK/FAR11.0004/06](#)

This certificate is issued as verification that the Service Facility and associated locations were assessed and found to comply with the IECEx Scheme requirements, relating to the type and scope of service listed above. This certificate is granted subject to the conditions as set out in IECEx Scheme Rules, IECEx 03 and Operational Documents as amended.

Approved for issue on behalf of the IECEx
Certification Body:

T. Pijpker

Position:

Certification Manager

Signature:
(for printed version)

Date:

2017-06-28

1. This certificate and schedule may only be reproduced in full.
2. This certificate is not transferable and remains the property of the issuing body.
3. The Status and authenticity of this certificate may be verified by visiting www.iecex.com or use of this QR Code.



Certificate issued by:

DEKRA Certification B.V.
Meander 1051
6825 MJ Arnhem
Netherlands

